SHIP: USS LASALLE (AGF-3) ITEM NO: 512-11-002

COAR: 16-537 PCN: EM02-3150

CMP: <u>NONE</u>

SURVEYOR: ASHBERRY

1. SCOPE:

1.1 Title: Ventilation; repairs

- 1.2 Location of Work:
 - 1.2.1 Aft Machinery Room Number 2 (7-136-0-E)
- 1.3 Identification:
 - 1.3.1 Ventilation Supply System 4-139-1

2. <u>REFERENCES</u>:

- a. Standard Items
- b. 501-4870232 Rev D, Ventilation General Notes for Surface Ships
- c. 501-4870233 Rev D, Ventilation Standard Details for Surface ships

3. REQUIREMENTS:

- 3.1 Accomplish a visual inspection of ventilation supply system (4-139-1) in its entirety for damage ventilation, insulation and missing parts, in the location listed in 1.2.
- 3.1.1 Accomplish repairs to the ventilation as determined by the visual inspection and as designated by the SUPERVISOR.
- 3.1.2 Provide 120 mandays of labor and 10,000 dollars of material to accomplish ventilation repairs identified in 3.1, when directed by the SUPERVISOR. Total cost greater or less than above manday and dollar amounts when authorized will be the subject of an equitable adjustment.
- 3.1.2.1 Submit four legible copies of a weekly report to document labor and material expenditures to the SUPERVISOR.
- 3.1.3 The new vent duct shall be the same size, type and design and installed in the same manner as that removed, using 2.b and 2.c for guidance.

SHIP: USS LASALLE (AGF-3)

- 3.1.4 Install new CRES Fasteners Class 304 (MIL-DTL-1222) and new gasket material (synthetic rubber medium soft 1/8 inch thick, symbol 2335, MIL-R-900) where required.
- 3.1.5 Install new metal tags with the contractors name, date and stating "PCB FREE" to all new/disturbed ventilation flanges, access covers and closures where gaskets are required.
 - 3.1.6 Chip and grind surfaces flush in way of new installations.
- 3.2 Accomplish the requirements of 009-12 of 2.a, including Table 3, Columns A, C and D, Lines One through 7.
- 3.3 Accomplish the requirements of 009-32 of 2.a for the new and disturbed surfaces.
- 3.4 Install new insulation to replace that damaged or missing in accordance with 009-11 of 2.a.

4. <u>NOTES</u>:

4.1 None.

5. GOVERNMENT FURNISHED MATERIAL (GFM):

5.1 None.

2 of 2 ITEM NO: 512-11-002